

L Number	Hits	Search Text	DB	Time stamp
12	80	(TSUBOI near1 MASAHIRO).in.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:06
-	108	control adj board and (motor same vehicle same electric)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:05
-	15681	electric adj vehicle	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/02/21 20:14
-	84	(electric adj vehicle) and board same (casing or housing)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2002/02/21 20:15
-	11	("4259603" "4633110" "4668898" "4673834" "4724347" "5049769" "5663604" "5691584" "5705868" "5841208" "5895994").PN.	USPAT	2002/02/22 11:25
-	1935	310/91	USPAT; US-PGPUB	2002/02/22 10:38
-	8	310/91 and ((pcb or (circuit adj board)) same rubber)	USPAT; US-PGPUB	2002/02/22 10:58
-	117	shaft same ((pcb or (circuit adj board)) same rubber)	USPAT; US-PGPUB	2002/02/22 10:54
-	1016	(310/68r).CCLS.	USPAT; US-PGPUB	2002/02/22 10:54
-	1	((310/68r).CCLS.) and ((pcb or (circuit adj board)) same rubber)	USPAT; US-PGPUB	2002/02/22 10:55
-	3	310/91 and ((pcb or (circuit adj board)) same grommet)	USPAT; US-PGPUB	2002/02/22 11:07
-	10	310/91 and ((pcb or (circuit adj board)) same sleeve)	USPAT; US-PGPUB	2002/02/22 11:07
-	1584	(310/90).CCLS.	USPAT; US-PGPUB	2002/02/22 11:25
-	112	((310/90).CCLS.) and sleeve adj bearing	USPAT; US-PGPUB	2002/02/22 11:26
-	3	((310/90).CCLS.) and ((sleeve adj bearing) same rubber)	USPAT; US-PGPUB	2002/02/22 12:12
-	6	("3644066" "4373861" "4564335" "4612468" "4737673" "4783608").PN.	USPAT	2002/02/22 11:41
-	16	4955791.URPN.	USPAT	2002/02/22 11:44
-	7	310/\$.ccls. and ((sleeve adj bearing) same rubber)	USPAT; US-PGPUB	2002/02/22 12:14
-	20	310/\$.ccls. and ((circuit adj board) WITH rubber)	USPAT; US-PGPUB	2002/02/22 12:28

-	35	electric adj motor and ((circuit adj board) WITH rubber) (310/dig.6).CCLS.	USPAT; US-PGPUB	2002/02/22 12:53
-	153		USPAT; US-PGPUB	2002/02/22 12:32
-	9	((310/dig.6).CCLS.) and rubber	USPAT; US-PGPUB	2002/02/22 12:32
-	1194	((circuit adj board) WITH rubber)	USPAT;	2002/02/22
-	33	(((circuit adj board) WITH rubber)) and rotor	USPAT; US-PGPUB	2002/02/22 12:51
-	5	("1688891" "2301425" "3330515" "3459977" "3527969").PN.	USPAT	2002/02/22 12:46
-	5	5444314.URPN.	USPAT	2002/02/22 12:49
-	2	jp-59050750-\$ did.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 12:52
-	1	electric adj motor and ((circuit adj board) WITH rubber)	EPO; JPO	2002/02/22 12:54
-	540	((circuit adj board) WITH rubber)	EPO; JPO	2002/02/22 12:55
-	2	((circuit adj board) WITH rubber)) and stator	EPO; JPO	2002/02/22 12:57
-	4	((circuit adj board) WITH rubber)) and rotor	EPO; JPO	2002/02/22 12:59
-	151	((circuit adj board) WITH rubber)) and electric	EPO; JPO	2002/02/22 12:59
-	1	((circuit adj board) WITH rubber)) and electric adj motor	EPO; JPO	2002/02/22 13:00
-	1	((circuit adj board) WITH rubber)) and winding	EPO; JPO	2002/02/22 13:02
-	3	((circuit adj board) WITH rubber)) and magnet	EPO; JPO	2002/02/22 13:03
-	38	310/91 and rubber and (circuit adj board)	USPAT; US-PGPUB	2002/02/22 13:04
-	1	wo-9733359-\$ did.	EPO; JPO	2002/02/22 16:52
-	1115	(310/91).CCLS.	USPAT; US-PGPUB	2002/02/22 16:53
-	1016	(310/68r).CCLS.	USPAT; US-PGPUB	2002/02/22 16:54
-	153	(310/dig.6).CCLS.	USPAT; US-PGPUB	2002/02/22 16:54
-	806	(310/64).CCLS.	USPAT; US-PGPUB	2002/02/22 16:56
-	826	(310/51).CCLS.	USPAT; US-PGPUB	2002/02/22 16:59
-	293	H02K005/24.ipc.	USPAT; US-PGPUB	2002/02/22 17:00
-	3259	H02K005/24.ipc.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:00

-	9099	H02K011/00.ipc.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:01
-	2416	H02K005/00.ipc.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:02
-	718	H02K005/18.ipc.	EPO; JPO; DERWENT; IBM_TDB	2002/02/22 17:02